IGS BURNER MODIFICATION REPORT

OUTLINE

Draft Report Due: Sept 7, 1993 (10 days plus holiday weekend)

Final Report Due: Sept 17, 1993

EXECUTIVE SUMMARY (<2 pages)

JKH

To address both Units 1 and 2

Success and Failures

SECTION 1 - INTRODUCTION & HISTORY

JKH

HISTORY

How we got here (acceptance test setup)
B&W Warranty considerations
Project installing T/C's

INSPECTIONS

History of degradation

PURPOSE OF PROJECT (why)

→ Unit descriptions

Resolve mechanical degradation of burners (was not to address and improve combustion)

GOALS

Address and resolve problems
Not to cause operational problems

EXPECTED RESULTS (what we wanted)

Resolution of overheat problems
Possible combustion improvements

SECTION 2 - PROJECT DEVELOPMENT

JHN

B&W INVOLVEMENT

Air Register Set-up Philosophy Out of service operation versus in-service Beef up existing design, no engineering evaluation Windbox measurement was solution to all problems

EER INVOLVEMENT

NEWKIRK INVOLVEMENT

RJM INVOLVEMENT

Aerodynamic evaluation Swirl Numbers Burner Balancing Flame Stabilizers Finite Element Analysis Petaled Back Plate Design

IPSC INVOLVEMENT Fuel Balancing

SECTION 3 - PERFORMANCE RESULTS

AEN

LOI Levels (original range)

NOx Levels

(explain NOx and LOI relationship)
Eyebrow Formation/ Ash Fusion Temperatures
Burner Front Temperatures
Flame Stability/ Scanners Operation
Combustion Stability (turndowns)
Burner Physical Inspections

?What didn't do:
 clinkers, drum level, CO, LOI, NOx
?AGASS Profiles??
?Economizer Temperature Profiles??

SECTION 4 - CONCLUSIONS & RECOMMENDATIONS

AEN

CONCLUSIONS

Burner Physical Integrity is good

Modifications were effective

Long life is expected

(U2 changeout not expected in foreseeable future)

Design looks good

Still Some Coal Nozzle Flaring

Burner Line Fires

Stabilizers were effective

Didn't cause catastrophic problems

(didn't burn or plug up)

Pushed flame out from burner

Holds stable flame thru load range

Corrected aerodynamic deficiencies of B&W design

Allowed effective setup of air registers

Secondary Air Balancing was effective
Shrouds and backplate settings allowed balancing on
outer and inner air to all 48 burners
Outer air doors control spin not volume
Inner burners are not starved for cooling air

Fuel Flow Balancing was effective
Fuel line balancing also helped on temperature profile

Backplate temperature have not been measured lowered Plus thermocouple concerns

Unit performance, NOx, LOI's are about the same or better

Economic Impact

How much cost and how much saved

What did RJM save us versus B&W design recommend

RECOMMENDATIONS

Continue to maintain stabilizers (keep)

No burner replacement for Unit 2 at this time, without petal back plate warpage may occur in the future and replacement may be required.

Continued periodic inspections

More investigative testing on flame front position to address coal nozzle flaring

More analysis into burner line aerodynamics to address burner line fires

More testing with non-directional velocity probe on fuel flow lines

ATTACHMENTS (poundage factor) Reference attachments in body of report!!!!

BURNER INSPECTION REPORTS/ PICTURES
TEST RESULTS
EER REPORT
NEWKIRK REPORT
RJM REPORT
B&W CORRESPONDENCE

Note: Be concise in writing, remember each section that you writ is not a stand alone document. All of the sections are needed to paint the whole picture. Try to stick to the point of view that you are writing. If you think of something that needs to be said that would best be covered in another section, write it and send electronically to the person covering that section. It is actual easier to add verbage to a report than to delete. When alot has be deleted because of redundancy, it becomes choppy and incoheren